




INSTALLATION INSTRUCTIONS

LUCCA80WBU/LUCCA80DBU



Required Tools



Screwdriver




Soft Hammer



Electric drill



Pencil





Level



Tape measure


Supplied Spare Part

(A) Hinges  X4	(B) 8x30-Doowels  X24
(C) Eccentric  X26	(D) Cams  X26
(E) Metal round feet  X4	(F) Clapboard towing  X4
(G) Hanging code  X1.5	(H) 3.9x25-screws  X6
(I) 3.9x37-screws  X6	(J) 4x50-screws  X6
(K) 5x60-screws  X2	(L) 12x60-Expansion Tube  X8
(M) angle iron  X1	(N) Hanging code hanging piece  X3
(O) 3.5x14-screws  X20	(P) shake hands  X2


(B) (D)




1



(C)



2



3

(B)

(I)

3


(C)

(I)




4

4


(C)






5




(C)








6





5



7



8









6


(H)  (P)  (F) 









9



(E)  (O) 



10




7




(L)



11




L1=166MM
L2=569MM
L3=L-132MM
L:Cabinet length





(J)



(N)





12




(K)




13



Hinge adjustment



14



SIKO KOUPELNY a.s.
Skorkovská 1310, 198 00 Praha 9
IČ: 26065801