









Instalační návod
Inštalacný návod
Mounting Instruction
Montageanleitung
Інструкція по установке

INCA50







1	x1	1800x255x16
2	x1	1800x255x16
3	x4	468x235x16
4	x2	468x212x16
5	x2	705x230x16
6	x2	705x230x16
7	x1	1719x240x3
8	x1	1719x240x3
		Σ=14






1




x2





2




3




4



5




6




7

8




x2




9

10



11



12

